






#### LEGEND

- MW-1  Monitoring well location and number
- B-2  Soil boring location and number
- CMW-4  Clearwater monitoring well location and number
-  Approximate excavation limits for 421 Santa Rosa Avenue site

Data for 421 Santa Rosa Avenue from Clearwater Group report dated September 20, 2005



APPROXIMATE SCALE (FEET)



Reference:

Ray Carlson & Associates, June 4, 2004



**Brunsing Associates, Inc.**  
5468 Skylane Blvd., Suite 201  
Santa Rosa, California 95403  
Tel: (707) 838-3027

Job No.: 691

Appr.: 

Date: 12/15/05

#### SITE MAP

505 Santa Rosa Avenue  
Santa Rosa, California

PLATE

2